

































1.1	HUS-HR	h_1	t_{fix}
	8x55	$65 \text{ mm} - t_{fix}$	0 ... 5 mm



2.1			
			
d_0	$\text{Ø } 8 \text{ mm}$		



4.1				
	SIW 14-A			
	SIW 22-A			
	SI 100			
	SIW 22T-A			
	35 Nm	