














		Use with					
X-BT-GF-N M8/7 SN8	✓	SF BT 22-A SF BT 18-A	DX 351 BTG	X-BT 1/4" - 20Nm/ 14,8 ft lb	Flange Nut M8	S-NS 13 C 95/3 3/4"	X-IG BT M8















10B

$T_{inst} = 16-20 \text{ Nm}$

SF 6-A22	1	5
SF 6H-A22	1	5
SF 10W-A22	4	11
SF 8M-A22	4	11
SFC 14-A	2	11
SFC 22-A	2	11



		Use with					
X-BT-GF-N M8/7 SN8	✓	SF BT 22-A SF BT 18-A	BX 3-BT (G)	X-BT 1/4" - 20Nm / 14,8 ft lb	Flange Nut M8	S-NS 13 C 95/3 3/4"	X-IG BT M8



11B

$T_{inst} = 16 - 20 \text{ Nm}$

SF 6-A22	1	5
SF 6H-A22	1	5
SF 10W-A22	4	11
SF 8M-A22	4	11
SFC 14-A	2	11
SFC 22-A	2	11